(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION	
PATENT NO. : 7,398,099 B2	Page1of1
APPLICATION NO. : 10/506,389	
ISSUE DATE : July 8, 2008	
INVENTOR(S) : Brouwer	
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:  In Column 8, Line 4, delete "2/90" and insert $2/\pi$ , therefor.	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

6300 Legacy, MS EVR 1-C-11 Plano, TX 75024 972-583-8656

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.

## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 7,398,099

**USPTO CONFIRMATION CODE: 1674** 

APPLICATION NO.: 10/506,389

PCT FILED: March 8, 2002

U.S. FILED: September 02, 2004

**EXAMINER: Matthew Anderson** 

**GROUP ART UNIT: 2618** 

FOR: SYSTEM AND METHOD FOR SPEED INDICATION THROUGH TRANSMIT POWER CONTROL COMMANDS

## 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION FOR USPTO AND/OR APPLICANT MISTAKE

## HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

SIR:

The following is a request for a certificate of correction in Serial Number 10/506,389, now Patent Number 7,398,099.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to our Deposit Account No. 50-1379.

The exact locations where the errors appear in the patent and patent application are as follows:

In Column 8, Line 4, delete "2/90" and insert - -  $2/\pi$  - -, therefor. (ORIGINALLY FILED SPECIFICATION DATED SEPTEMBER 2, 2004, PAGE 11, LINE 14)

The requested corrections are attached on Form PTO 1050.

	Respectfully Submitted
Dec. 22, 2008	/SIDNEY L. WEATHERFORD,Reg#45602/
DATE	Sidney L. Weatherford
	Registration No. 45602
	Attorney of Record